

PROFORMA FOR THE SAFETY OF SCHOOL BUILDING PART- 1

(To be filled by the Head of School/ Institute)

1. Name of the School
2. Location
3. Plot Area
4. Plinth Area
5. Number of Storey's
6. Year of Construction of Building
7. If the building has been constructed under the supervision Of the qualified Engineer, the following details may be given
 - a) Name of the Engineer with qualification
 - b) Address of Engineer
 - c) Set of Structural drawings used in the construction, if available
 - d) Name & address of Architect with qualification
8. Whether the building has been constructed for the purpose
 - a) School
 - b) Residential Purpose and converted for use as a School
9. Materials used for roofs
 - a) R.C.C. Slabs/R.B.C. Slabs
 - b) R.S. Joist & Battons
 - c) Wooden joists & Battons
10. Materials used for walls
 - a) Mud Mortar
 - b) Cement Mortar
 - c) Lime Mortar
11. Flooring
 - a) Conglomerate
 - b) Terrazo
 - c) Brick Paving.
12. A detailed drawing indicating dimensions of the rooms Alongwith size and location of doors and windows (Attached)

Global Sparks Convent International School
MJK Nagar, Bapu Market, Lohara
6000 Sq. Yards
12246 sq. ft
Ground
2023
S.S. Beains and Associates
Indira Colony, Chandigarh
Road, Loh.

YES/ NO

YES/ NO ✓

YES/ NO

YES/ NO ✓

YES/ NO ✓

YES/ NO ✓

YES/ NO

YES/ NO

YES/ NO ✓

YES/ NO ✓

YES/ NO ✓

Signature with Stamp of the seal
Principal
Global Sparks Convent International School
MJK Nagar, Bapu Market, Lohara.
Mob : 81980-43723

• PART-II
(To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated ..21/11/25..... And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safely occupied for normal use upto (indicate upto which it can be used)31/3/28.....

[Signature]
Sub Divisional Engineer,

Sub Divisional Engineer
Provincial Division No. 3,
P. W. D. B & Br., Ludhiana.
[Signature]

Principal
Global Sparks Convent International School
WJK Nagar, Bani Market, Lahore.
MOP: 81880-4353